

SW Cor. Sec 28, T17S-R4W
Found: 5/8" rebar
Origin: unknown

N 0° 00' 00" E (assumed) 1332.40'

SEE Pg. 2 for
Parcel Details

S 1/2, S.W. 1/4
Sec. 28, T17S-R4W
Toll Farms Inc.
BLK 227, Pg 596

N 1/2, S.W. 1/4
Sec. 28, T17S-R4W

W. 1/4 Cor. Sec 28, T17S-R4W
Found: 5/8" rebar
Origin: unknown

N 1/4 Cor. Sec 28
T17S-R4W
Found: Iron T" Bar w cap
Origin: BLM

Legend
▲ = section corner found
△ = section corner set
1/2" x 24" rebar w/ I.D. cap
\$ = section line
X = "MAG" nail in asphalt

(N 0° 45' 13" E)
5307.85'

2655.09'

E 1/4 Cor. Sec 28, T17S-R4W
Found: bent 5/8" rebar,
replaced w 1/2" x 24" rebar
Origin: unknown

(S 88° 47' 06" E)
5341.427'

For: Toll Farms Inc.
c/o Tom Toll
2453 10th Avenue
Lindsborg, KS 67456

Date: 4-6-2007

(N 0° 45' 13" E)
2652.75'

1326.38'

S 88° 54' 36" E
2645.77'

2628.22'

N 89° 02' 12" W

Section Break down for Toll Survey W. of creek in
the S 1/2, S.W. 1/4 Sec. 23, T17S-R4W.
Pg. 3/3
Heller Boundary Surveys, W.B. Heller L.S. 1202, 863 S. 9th, Salina KS 67401