

- NW Cor. 4-18-01  
Fd. 1" Pipe Origin Unknown  
1. 56' NW to spk top fc. post  
2. 45.2' SW to spk/wshr util. marker post  
3. 39.9' SE to spk/wshr in power pole

Surveyor Note: Township Operator dug for N $\frac{1}{4}$  Cor. 4-18-1 on Sept. 12, 2005 and found no monument (wood or stone). This surveyor extended line from west per sketch and record GLO survey.

2641.25' CM N90°E Assumed Bearing

(Survey Rec. 2646.0' 1931-1941)

Section 5, T18S, R1W

1323.00 CM

Pin Set 33' N. of Section Line  
per Township Road R/W

- N1/4 Cor. 5-18-01  
Fd. 5/8 Bar Placed ID cap  
Origin Unknown  
1. 32.2' N to spk in fc. post  
2. 41.4' SW to spk in top gate fc. post  
3. 39.5' NE to spk in top gate fc. post

Section 4, T18S, R1W

Scale 1"=800'

- Set 24" pins with ID cap
- △ Found Monument



McPherson Engineering  
& Land Surveying Services  
PO Box 662  
McPherson, KS 67460  
620-241-0950

- SW Cor. 4-18-01  
Fd. 3/4" Pipe origin unknown  
1. 42.6' SW to spike in fc. post  
2. 31' SW to west end RCP  
3. 30' SE to spike east end RCP

5432.36' CM S1°14'41"E

West Half of West Half Section 4

1428.50' CM

1334.41' CM

1334.41' CM

1334.41' CM

21.41' Ch. C. Pro. Rec.

40 ch rec.

40 ch rec.

40 ch rec.

Pin Set 33' N. of Section Line  
per Township Road R/W

1321.42' CM

1321.42' C

2642.84' CM N89°58'27"E

M = Measured  
C = Calculated  
Ch = Chains  
Pro = Prorated

Client Jim O'Connor  
PO Box 3037  
Idaho Springs, CO 80452

- S1/4 Cor. 4-18-01  
Reset 1/2" bar and cap per ref. notes  
1. 35' S. to fence line, 3.2' E to corner post and line to south  
2. In split of double hedge rows to north  
3. 28.3' NNE to spike in corner fence post  
4. 36.2' SE to spike in top corner fence post

I, Melanie L. Thrower, performed above survey on September 14, 2005. This exhibit is a true representation of said survey.