

Plat of Survey

Heller Boundary Surveys, William B. Heller, L.S. 1202
863 S. 9th St., Salina, KS 67401 Ph: 785-819-2557

W. 1/4 Cor., Sec 21, T21S-R2W

Found 1/2" rebar
Origin unknown

For. Jay R. & Linda K. Goering
2002 Arrowhead Road
Moundridge, KS
67107

Date: 1-10-2006

