

Plat of Survey
Heller Boundary Surveys, 863 S. 9th St., Salina, KS, 67401
William B. Heller, L.S. 1202, Ph 1-785-825-1737

For: Ronald D. Erickson
1770 15th Avenue
McPherson, KS 67460

'NW Cor., Sec. 24, T18S-R3W
Found 1/2" rebar & I. D. cap
Origin: unknown

N¹/₄ Cor. Sec 24, T18S-R3W
Found 1/2" I.D. cap
Rebar origin Landmark
Surreying & Mapping

Ronald D. & Dawn Erickson
NW 1/4 Sec. 24, T18S-R3W

Legend

Scale: $1'' = 440'$

▲ = Section Corner

- = set 1/2" rebar with I.D. cap

0 = Found Macropods

$\mathcal{P}$ = property line

\$ = section line

P.O.B. = point of beginning

R/W = road right of way

- No Pin Set (Macon position)

Center Cor Sec. 24, T18S-R3W
Not Set (Macon position)

Pg. 2/2

S. 1/4 Cor., Sec 24, T18S-R3W
Found 5/8" rebar, origin unknown

Date: 2-8-2006

W. $\frac{1}{4}$ cor., Sec 24, T18S-R3W
Found: 1" iron pin
Origin: unknown