

10 Ac, Marlin Rummel Survey

1-27-06



Center Corner
Sec. 26, T18S-R1W
Found 6"x6" sandstone
Origin: unknown

Scale: 1" = 440'

SE 1/4, Sec 26, T18S-R1W


▲ = Section Corner Monument

• = 1/2"x24" rebar with I.D. cap

P = property line

± = section line

R/W = road right of way



SW Cor Sec 26
T18S-R1W
Found 4"x12" sandstone
Origin: Garber Surveying Service

S 1/4 Cor. Sec. 26,
T18S-R1W
Found bent 3/4" iron
pin with 800 spk.
Origin Unknown

Heller Boundary Surveys
William B. Heller, L.S. 1202
863 S. 9th St.
Salina, KS 67401
Ph: 1-785-819-2557

For: Marlin Rummel
2531 Hwy 56
Canton, KS
67428

Plat of Survey

Date: 1-28-2006

Pg. 2/2