

Heller Boundary Surveys, William B. Heller, L.S. 1202, 863 S. 9th, Salina, KS 67401, cellular: 620-245-8023
Plat of Survey of the S.W. 1/4 Section 27, T17S-R2W

W. 1/4 Cor, Sec. 27, T17S-R2W
Found: 5/8" rebar
Origin: unknown

2,642.89' (P.S.)
S 89° 09' 21" W 2,642.89'
2,122.89'

Center Cor, Sec 27, T17S-R2W
Found: 5/8" rebar
Origin: unknown

2,640.00' (G.L.O.)
2,642.98' (P.S.)
2,642.98'

50° 49' 39" E

S.W. 1/4, Sec. 27, T17S-R2W
except parcels.
Donald L. Sr. & Jan Burgett,
Trustees of the Donald L. Sr.
Trust U/A dated August 2,
1994.

Parcel described
11.5 Ac

Ronald Burgett
Parcel in the S.W. 1/4 Sec. 27, T17S-R2W
Deed Bk. 264, Pg. 412
20 Ac

Giesel Parcel

Thye Family Tr. Parcel

S.W. Cor., Sec 27, T17S-R2W
Found: 5/8" rebar
Origin: unknown

N 89° 03' 29" E 2,650.35'
2,650.35' (P.S.)
2,640.00' (G.L.O.)
Sioux Road

S. 1/4 Cor., Sec. 27, T17S-R2W
Found: 5/8" rebar
Origin: unknown

Scale: 1" = 330'

Legend

- ▲ = Section Corner Found
- = 1/2" x 24" rebar & I.D. cap set
- P.O.B. = Point of Beginning
- ⌘ = section line
- ⌘ = property line
- (P.S.) = Previous Survey
- (G.L.O.) = Original General Land Office

For: Ronald Burgett
2146 Sioux Road
Gypsum, KS 67448

Date: December 20, 2011

Note: All distances are calculated / measured distances unless otherwise noted.