

Heller Boundary Surveys, William B. Heller, L.S. 1202, 863 S. 9th, Salina, KS 67401, cellular: 620-245-8023
 Plat of Survey of the S.W. 1/4 Section 27, T17S-R2W

W. 1/4 Cor., Sec. 27, T17S-R2W
 Found: 5/8" rebar
 Origin: unknown

Center Cor., Sec. 27, T17S-R2W
 Found: 5/8" rebar
 Origin: unknown

2,640.00' (G.L.O.)
 2,642.98' (P.S.)
 2,642.98'

S.W. 1/4, Sec. 27, T17S-R2W
 except parcels:
 Donald L. Sr. & Jan Burgett,
 Trustees of the Donald L. Sr.
 Trust U/A dated August 2,
 1994.

Parcel described:
 20.5 Ac

Scale: 1" = 330'
 Legend

- ▲ = Section Corner Found
- = 1/2" x 24" rebar & I.D. cap set
- P.O.B. = Point of Beginning
- ⌘ = section line
- ℙ = property line
- (P.S.) = Previous Survey
- (G.L.O.) = Original General Land Office

For: Ronald Burgett
 2146 Sioux Road
 Gypsum, KS 67448

Date: January 16, 2012

S.W. Cor., Sec. 27, T17S-R2W
 Found: 5/8" rebar
 Origin: unknown

S. 1/4 Cor., Sec. 27, T17S-R2W
 Found: 5/8" rebar
 Origin: unknown

Note: All distances are calculated / measured distances unless otherwise noted.