


Plat of Survey

Heller Boundary Surveys, William B. Heller, L.S. 1202
863 S. 9th St., Salina, KS 67401, PH: 1-785-825-1737

Date: 2-20-2007
For: Michael R. Anderson
1030 2nd Ave.
Windom, KS
67491



Marion M. & Geraldine M. Trust
S.W. 1/4 & S. 1/2 of S.E. 1/4, Sec. 9,
T20S-R5W
Bk. 246, Pg. 355

Legend

- ▲ = section corner
- = 1/2"x24" iron rebar and I.D. cap
- P.O.B. = point of beginning
- PL = property line
- SL = section line