

Heller Boundary Surveys, William B. Heller, L.S. 1202, 863 S. 9<sup>th</sup>, Salina, KS 67401, cellular: 620-245-8023  
 Plat of Survey of the S.W. 1/4 Section 27, T17S-R2W

W. 1/4 Cor, Sec. 27, T7S-R23  
Found: 5/8" rebar  
Origin: unknown

2,642.98, (G.L.A.)  
2,642.98, (P.S.)  
2,642.98

S.W. 1/4, Sec. 27, T17S-R2W  
except parcels.  
Donald L. Sn. & Jan Burgett,  
Trustees of the Donald L. Sn.  
Trust U/A dated August 2,  
1994.

Parcel described:  
20.5 Ac

Center Cor, Sec 27, T17S-R2W  
Found: 5/8" rebar  
Origin: unknown

Scale: 1" = 330'

Legend

▲ = Section Corner Found  
 ○ = 1/2" x 24" rebar in I.D. cap set  
 P.O.B. = Point of Beginning  
 § = section line  
 R = property line  
 (P.S.) = Previous Survey  
 (G.L.O.) = Original General Land Office

For: Ronald Burgett  
2146 Sioux Road  
Gypsum, KS 67448

Date: January 16, 2012

S.W. Cor., Sec 27, T17S-R2W  
Found: 5/8" rebar  
Origin: unknown

N 89° 03' 29" E      2,650.35'  
Sioux Road      2,650.35' (P.S.)  
                         2,640.100' (G.L.O.)

S. 1/4 Cor., Sec. 27, T17S-R2W  
Found: 5/8" rebar  
Origin: unknown

Note: All distances are calculated/measured distances unless otherwise noted.