NW Cor. 4-18-01 Surveyor Note: Township Operator dug for Fd. 1" Pipe Origin Unknown N¹/₂ Cor. 4-18-1 on Sept. 12, 2005 and found 1. 56' NW to spk top fc. post no monument (wood or stone). This surveyor 2. 45.2' SW to spk/wshr util. marker post extended line from west per sketch and 3. 39.9' SE to spk/wshr in power pole__ record GLO survey. 2641.25' CM N90°E Assumed Bearing (Survey Rec. 2646.0' 1931-1941) 1323.00 CM Pin Set 33' N. of Section Line Section 5, T18S, R1W per Township Road R/W -N1/4 Cor. 5-18-01 Fd. 5/8 Bar Placed ID cap Origin Unknnown Section 4, T18S, R1W 1. 32.2' N to spk in fc. post 2. 41.4' SW to spk in top gate fc. post 3. 39.5' NE to spk in top gate fc. post Scale 1"=800" Set 24" pins with ID cap Δ Found Monument William Control McPherson Engineering & Land Surveying Services PO BOx 662 MCPherson, KS 67460 620-241-0950 SW Cor. 4-18-01 Fd. 3/4" Pipe origin unknown 1. 42.6' SW to spike in fc. post 2. 31' SW to west end RCP 3. 30' SE to spike east end RCP_ —Pin Set 33' N. of Section Line per Township Road R/W 1321.42' C M = Measured 1321.42' CM C= Calculated 2642.84' CMN89°58'27"E Ch = Chains S1/4 Cor. 4-18-01 Pro = Prorated Reset 1/2" bar and cap per ref. notes 1. 35' S. to fence line, 3.2' E to corner post and line to south Client Jim O'Connor 2. In split of double hedge rows to north 3. 28.3' NNE to spike in corner fence post PO Box 3037 4. 36.2' SE to spike in top corner fence post_/ Idaho Springs, CO 80452 I, Melanie L. Thrower, performed above survey on September 14, 2005. This exhibit is a true representation of said survey.

http://www.adultpdf.com