

Heller Boundary Surveys, W.B. Heller, L.S. 1202, 863 S. 9th, Salina, KS 67401
Ph: 1-785-825-1737 Email: wheller@ks-usa.net

Date: 4-6-2007

For: Toll Farms Inc,
c/o Toll Toll
2453 10th Avenue
Lindsborg, KS 67456


Legend:
▲ = section corner monument
● = 1/2"x24" rebar w/ I.D. cap
P.O.B. = point of beginning
\$ = section line
R/W = property line
R/W = road right of way

W. 1/4 Cor, S.W. 1/4 Sec 28, T175-R24W
Set "MAG" nail in asphalt
Origin: W.B. Heller

N 88° 54' 36" W
2645.77'

C.S. 1/16 Cor. Sec. 28
T175-R24W
Set 1/2"x24" rebar w/
I.D. cap.
Origin: W.B. Heller

S 0° 00' 00" W (assumed)
1,332.40'



S.W. Cor. Sec. 28,
T175-R24W

Found: 5/8" rebar
Origin: unknown

2628.22'
S 89° 02' 12" E

S. 1/2, S.W. 1/4, Section 28
T175-R24W
Toll Farms Inc. Bldg. 596

S. 1/4 Cor. Sec. 28,
T175-R24W

Found: 5/8" rebar
Origin: unknown

Scale:
1" = 330'