

SWCor. Sec 28, T17S-R4W

http://www.admiresoft.com
Created by TIFF To PDF trial version, to remove this mark, please register this software.

Found 5/8" rebar

Origin: unknown

NO^o 00' 00" E (assumed)

1332.40'

1332.40

SEE Pg. 2 for
Parcel Details

Legend

▲ = section corner found

△ = section corner set

1/2" x 2" rebar w/ T.D. cap

\$ = section line

△ = "MAC" nail in asphalt

Scale:
1" = 660'

W. 1/4 Cor. Sec 28, T17S-R4W
Found: 5/8" rebar
Origin: unknown

5 88° 47' 06" E

(NO^o 45' 13" E)
5307.85'

2RM
331

2,663.34"

\$

N. 1/2 S.W. 1/4
Sec. 28, T17S-R4W

For: Toll Farms Inc.
C/o Tom Toll
2453 10th Avenue
Lindsborg, KS 67456

Date: 4-6-2007

588° 54' 36" E

\$

2652.75'

(NO^o 45' 13" E)

5 1/4 Cor. Sec. 28, T17S-R4W
Toll Farms Inc.
BL 227, Pg 596
2,628.22'
N 89° 02' 12" W

S 1/2 S.W. 1/4
Sec. 28, T17S-R4W

2,645.77'

\$

1326.38'

\$

2678.09'

(5 88° 47' 06" E
5341.427,)

E 1/4 Cor. Sec 28, T17S-R4W
Found: bent 5/8" rebar,
replaced w/ 1/2" x 2" rebar
Origin: unknown

2,655.09'

N 1/4 Cor. Sec 28
T17S - R4W
Found: Iron "T" Bar w/ cap
Origin: BLM

Section Break down for Toll Survey W. of creek in
the S. 1/2, S.W. 1/4 Sec. 23, T17S - R4W.

Pg. 3/3

Heller Boundary Surveys, W.B. Heller L.S. 1202, 863 5.9th, Salina KS 67401