SURVEYOR'S REPORT

http://www.adultpdf.com

Created by TIFF To PDF trial version, to remove this mark, please register this software.

The following description of record was furnished us with a request for a survey of the same:

Tract in Southeast 4 Sec. 26, T.19 S., R.2 W.

Beginning at a point 132.33 Rods South of the Northeast corner of said Southeast 1 section; Thence West 160 Rods; Thence South 15.02 Rods; Thence East 12.65 Rods; Thence South 12.65 Rods; Thence East 147.35 Rods; Thence North 27.67 Rods to the place of beginning.

While implying the same through East-West calls and North-South calls each adding up to 2640 ft., no mention is made in the above description of the East, West, or South lines or of the Southeast corner of said Southeast 4. The acreage of the above described tract was also not included, but the conclusion was that the Southeast 4 was assumed to be regular, and containing 160.0 Acres.

No reference ties or other information being available for locating the Northeast and Southwest corners of the Southeast 4, their locations were established as follows:

Southwest corner Southeast \(\frac{1}{4}\) - a straight line split was established between the South section corners of Section 26 as per the original record survey. Extensive digging unearthed no trace of the cornerstone of record and at that point a 5/8" x 24" iron bar was set and referenced for the South \(\frac{1}{4}\) corner of Section 26.

Northeast corner Southeast ¼ - From computations, the straight line split between the East section corners of Section 26, as per the original record survey, was determined to fall in the midst of a maze of criss-cross pipe lines where it was dangerous to and not possible to conduct heavy excavation to search for the cornerstone at a point some 20 ft. East of the middle of the graded road. The graded road essentially split hedges East and West, and that entire area, some 20 ft. x 20 ft. x 3+ ft depth, was excavated carefully in search of either the original stone or one set later by Tourney 10.56 ft. North of the original stone by consent. Unearthing no trace of either stone, a 5/8" x 24" iron bar was set and referenced on the straight line split for the East ¼ corner of Section 26.

The early split of the Southeast ¼ of Section 26, Township 19 South, Range 2 West of the 6th P.M. was intended as an inheritance split into six equal parts and was described in Rod increments, i.e. 26.667 Rods (440.0 ft.) along the East line of said Southeast ¼. For identification and clarity these parcels are shown by dashed lines running East to West and are numbered 1 to 6 from the North on the accompanying plat of survey.

To maintain equal acreage distribution, when a trade was made of the South 1 Rod of the parcel #3 for a 1 acre square in the Southeast corner of said Southwest 1 (Southwest corner of parcel #6), the division lines were shifted North 1 Rod for the South lines of parcels #4 and #5, resulting in an unusual combination of parcels and acreages through conveyances to the present day, none of which having been surveyed and properly described.