

bearings and distances for the intersection of straight lines between the opposite $\frac{1}{4}$ corners. From the relative coordinates a $5/8$ " x 24" iron bar was set and referenced for the center corner of Section 34.

Further survey work was only to except a certain portion of the Southwest $\frac{1}{4}$ and describe separately for our clients.

It should be noted that of four corners referenced and sought, no references remained for three corners, and one, the Southeast corner of Section 34 was not discovered and presumed lost. Also of five corners found, only three were believed referenced, two of which all references were missing. For those only a detection device enabled their location. Thus three corners found and used could not be absolutely identified or verified for authenticity.

This survey is signed "to the best of my knowledge and ability".

Respectfully submitted,

William H. Klassen
William H. Klassen

