Created by TIFF To PDF trial version, to remove this mark, please register this software.

SUIVEY IOT: David Willems By: Garber Surveying Service, P.A. 217 East First Ave., Suite #9 Hutchinson, Kansas 67501 DESCRIPTION: A tract in the S.E. & of Section 30, T.21 S., R.5 W. of the 6th P.M. as more particularly described on the attached sheet. -N.4-COR. SEC. 30 T.215. R.5W. Δ - Section subdivision FOUND IRON PIN, corner found • - 5/8"x24" capped rebar set SCALE: 1"=100" 510.00 2138.30 510,00 2648.30 J-S.4 COR SEC. 30 T. 218. R SW.; FOUND S.E. COR. SEC. 30 T. 215. R.5W. BROKEN L.S.; SET 98'X24" FOUND IRON PIN. IRON REBAR THROUGH CTR. I hereby certify this plat to be a true, correct and complete representation of a survey made by me of the property described above and on the attached sheet \$ this 14th day of September, 1981, Daniel E. Garber, R.L.S.