

William B. Hetter, P.S. 1202, cellular: 620-245-8023, email: willyboskilly@yahoo.com
863 S. 9th Street, Salina, KS 67401

Found: 5/8" rebar
Origin: References at
MPCo.

P.O.B. Parcels 1 & 2

Note: All distances are calculated- measured distances.
Note: Field work performed in April 2020.

W. 1/16, N. W. 1/4 Sec. 11
TZ15-R5W
Set: 1/2" x 24" rebar & I.D. cap
Origin: W.B. Heller

W 1/4 Cor. Sec. 11, T21S-R5W
Found: 1 1/2" rebar $\pm$ I.D. cap
Origin: W. B. Heller

863 S. 9th Street, Salina, KS 67401


(assumed)
N89°44'49"E

2,628.78' (G.L.O.)

2,638.89'

N. 1/4, N.W. 1/4 Sec. 11, T21S-R5W
Set: 1/2" x 24" rebar in I.D. cap
Origin: W.B. Hecker

N. 1/4 Cor., Sec. 11, T21S-R5W
Found: 3/4" rebar
Origin: References at MP Co.



Scale: $1'' = 220'$

Legend

- ▲ = Section Corner Monument
- = 1/2" x 24" rebar I.D. cap
- P.O.B. = Point of Beginning
- ± = Section Line
- PL = Property Line
- R/W = Public Road Right of Way
- (Ps) = Previous Survey
- (G.L.O.) = General Land Office

For: Gordon D. Enns
449 Cheyenne Road
Inman, KS 67546
Date: April 10, 2020

2,637.99' E. 1/4 Cor. Sec. 11, T215-R5W
 Found: 1/2" rebar @ I.D. cap
 Origin: W.B. Heller
 N89°04'21"17"

5 1/4 Cor., Sec. 11, T215-R5W
 Found: 1/2" rebar @ "Alpha" I.D. cap
 Origin: Alpha Land Surveys

Pg. 3/3