

Plat of Survey

Heller Boundary Surveys, W. B. Heller, L.S. 1202, 863 S. 9th, Salina, KS 67401 Ph: 1-620-245-8023

Physical position of possession lines at approx. N. 1/4 Cor. position. No. Section Corner found.

N.E. 1/4 Sec. 12, T18S-R3W
Found: 5/8" rebar & I.D. cap
Origin: W.B. Heller

W. 1/4 Cor., Sec. 12, T18S-R3W
Set: 1/2" x 24" rebar & I.D. cap
Origin: W.B. Heller

S 1° 25' 56" E
2,609.18'

This position correct in N.-S. location (1/4 §) only.

1/4 Section Line

N 0° 30' 18" W
2,679.39'

Approximate 1/4 Section Line

S 88° 26' 08" W 5,275.58'

N 0° 19' 45" W
2,648.55'

E. 1/4 Cor., Sec. 12, T18S-R3W
Found: 5/8" rebar & I.D. cap
Origin: Helaine L. Throver

Stream

33' R/W

N 0° 19' 03" W
2,643.91'

N 88° 48' 45" E
2,612.16'

N 88° 48' 24" E
2,612.02'

S.W. Cor., Sec. 12, T18S-R3W
Found: 1/2" rebar
Origin: unknown

S. 1/4 Cor., Sec. 12, T18S-R3W
Found: 1/2" rebar & I.D. cap
Origin: Landmark S. & M, Inc

S.E. 1/4 Cor., Sec. 12, T18S-R3W
Found: 5/8" rebar
Origin: unknown

For: Jay Scott
P.O. Box 136
110 Memory Lane
Roxbury, KS 67476

Section Twelve (12), T18S-R3W of 6th P.M.

Date: January 17, 2011

Note: All distances are calculated/measured distances.



1" = 660'
Scale

Legend

- ▲ = Section Corner Monument Found
- △ = Section Corner Set
- = Physical position only
- = "60D" spike set on 1/4 Section line
- *** = fence line
- § = Section Line

Certificate:

1/4 Section Line Sec. 12, T18S-R3W
Surveyed by W.B. Heller
L.S. 1202 on 1-17-2011
W.B. Heller
LAND SURVEYOR
KANSAS
1-17-2011