

Brent & Roxie Sneath
372 Dakota Road
Windom, KS 67491

SE corner 15-T20S-R5W
Found mag nail 2" below surface- above $\frac{5}{8}$ bar


1. 68.7' SW to NE corner building
2. 39.35' NW to spike in SW side power pole
3. 45.20' SE to spike in top corner fence post
4. 1' east to center travel way N-S
5. 5' S to center travel way E-W

NE Corner S₂, SE₄ 15-T20S-R5W
Found magnetic nail in asphalt 3" below surface

1. 39.25' SW to 1st T post
2. 37.15' NW to nail in 2nd hedge post
3. 33.05' WSW to concrete post
4. In line with hedge to west
5. 1' west of center travel way.

A part of the South Half of the Southeast Quarter (S $\frac{1}{2}$ SE $\frac{1}{4}$) of Section 15, Township 20 South, Range 5 West of the 6th P.M. described as follows: Beginning at the SE corner of said SE $\frac{1}{4}$ Section 15 thence west along the south line of said SE $\frac{1}{4}$ 1592.00'; thence N1°56'30"E 636.05'; thence S89°36'04"E 555.14'; thence S2°23'40"E 145.52'; thence N80°26'40"E 261.76'; thence N1°17'23"W 786.42' to the north line of said S $\frac{1}{2}$ SE1/4; thence S89°54'14"E along said north line 774.60' to the east line of said SE1/4; thence S00°15'06"W along said east line 1314.80' to the point of beginning containing 34.25 acres including the east and south 33' thereof for road easement and any other easements of record.

On September 3, 2003 this survey was completed in the field by
Melanie L. Thrower, Kansas licensed land surveyor no. 1297.



Scale 1"=500'

1319.26'

N 0° 08' 21"E 2637.11' R 2638.52' M

-Center 15-T20S-R5W
Found Stone 6" below surface
Set Rebar at North Edge Stone
1. at west edge of hedge post and hedge tree
2. in line of fence to north, west, south, and east

SW Corner, E1/2, SW1/4 15-T20S-R5W
Found RR Spike
1. 33' N. to 5/8" Bar by Durr 1994
2. 30' N. to corner fence post
3. 35.8' NE to T Post
42.4' NE to spike in north face power pole
5. 6' N to center travel way

