

Plat of Survey

Heller Boundary Surveys, W.B. Heller L.S.,
863 S. 9th St., Salina, KS 67401
Ph: 1-785-819-2557 Email: wheller@ks-usa.net

For: Harold D. Hazelton
1052 Navajo Road
McPherson, KS 67460

Date: 5-22-2007

Report of Survey: Survey requested by Harold D. Hazelton for fence line. location on N.-S. $\frac{1}{4}$ section line. The S. line of the N.W. $\frac{1}{4}$ was also located. The Center Corner of Sec. 2, T19S-R4W was set at the intersection of the $\frac{1}{4}$ corners of Section 2, T19S-R4W. References for Section Corners found at the McPherson Co. Public Works Vault. Angles and distances read with a Nikon DTM 521 Total Station.

Location:

Section 2, T195-R4W



Note: No monument set at the N. $\frac{1}{16}$ Cor., N.W. $\frac{1}{4}$, Sec. 2.
T19S - R4W. Monument set at R/W East of this position. Pg. 11

Pg. 1/1

