


Plat of Survey

Holler Boundary Surveys, William B. Heller, L.S. 1202, 863 S. 4th, Salina, KS 67401
 Ph: 1-785-825-1737, email: wheller@ks-usa.net



Note: A Bearing of S90°00'00"E is assumed on section line.