
CORNERSTONE SURVEYING

Richard Langley 785-823-6011 FAX 785-820-9693 P.O. Box 2745 Salina, Kansas 67402

LEGEND:

(p) Platted

(m) Measured (c) Calculated



W 1/4 corner Sec 24, T17S, R5W

Section Corner Ties:

W 1/4 corner Sec24, T17S, R5W FOUND 3/8" rebar - T fence post on South side 3" above bar 25.25' E.S.E. to step spike in footing N.W. corner building 77.50' W.S.W to step spike in power pole 100.70' N.N.W. to step spike in meter pole

Southeast corner Sec23, T17S, R5W FOUND 2" cap on rebar Steel fence post on South side of bar 12.0' N.E. to spike in 12" Elm Tree 8.40' N.N.W. to spike in 6" Ash tree 31.50' W.N.W. to spike in 4" Elm Tree E 1/16 corner of the NE 1/4 Sec 26, T17S, R5W FOUND 5/8" rebar w/Plastic cap 9.65' South to spike in 300" mulberry tree 15.20' South to 5 to spike in 20" hackberry tree 10.00' South to East-West tree line In line w/ tree line going North