

Plat of Survey



Heller Boundary Surveys, W. B. Heller, L.S. 1202, 863 S. 9th,
Salina, KS 67401, Ph: 1-620-245-8023

Mohawk Road

N. 1/4 Cor. Sec. 17, T19S-R5W
Found: 5/8" rebar, Origin: unknown.


2,639.34 (G.L.O.) T19S-R5W

N.E. Cor Sec 17,
Found: 5/8" rebar
Origin: unknown
P.O.B.




Scale: 1" = 200'

5.7 Ac, incl. R/W



597.63'
N89°32'33"E

N. 1/2, N.E. 1/4 Sec. 17,
T19S-R5W
Keith D. & Linda Family
Trust
Deed Bk. 648, Pg. 2712



2ND Avenue

2,178.22'
Bearing Assumed
on this

E. 1/4 Cor. Sec 17, T19S-R5W
Found: 5/8" rebar & I.D. cap
Origin: Garber Surveying Service

Legend

- ▲ = Section Corner Found
- = 1/2" x 24" rebar & I.D. cap
- P.O.B. = Point of Beginning
- ⌵ = Section Line
- ⌵ = Property Line
- R/W = Public Road Right of Way
- G.L.O. = General Land Office (Original Subdivision)

For: Richard Ensz
233 Mohawk Road
Windom, KS 67491
Date: April 17, 2012

Note: All distances are calculated/measured distance unless otherwise noted.