

DURR ENGINEERING,
525 HOWARD
HUTCHINSON, KS. 67501
316-663-9613

5/4/2000

REPORT OF SURVEY

TRACT IN THE NORTHEAST QUARTER OF SECTION 16, TOWNSHIP 20 SOUTH, RANGE 2 WEST,
McPHERSON COUNTY, KANSAS:

FOUND 5/8" BAR AT THE NORTHEAST CORNER 16

FOUND 5/8" BAR AT THE NORTHWEST CORNER 16

FOUND 5/8" BAR AT THE SOUTHEAST CORNER 16

SET NAIL OVER PK NAIL AT SOUTHEAST CORNER OF SECTION 21

FOUND APPROX SOUTHEAST CORNER SECTION 15

PRODDED HARD FOR STONE AROUND INTERSECTION, NOTHING FOUND

MEASURED FROM POINT IN INTERSECTION OF 15, 16, 21, 22:

WEST TO SW 16 - 5318.85'
SOUTH TO SE 21 - 5256.55'
EAST TO SE 15 - 5263.33'
NORTH TO NE 16 - 5256.35'

MY DECISION WAS TO SPLIT NORTH SOUTH DISTANCE BETWEEN 16 & 21 IN HALF. THIS PUT THE
CORNER APPROX 3 FEET NORTH OF APPARENT INTERSECTION CENTERLINE AND CENTER EAST
WEST.

SPLIT THE MILE ON EAST LINE OF 16. THIS PUT THE CORNER 3' SOUTH OF FENCE LINE, I
USED THE CENTER OF THE ROAD AND HAD A DEFLECTION OF $SO^{\circ}17'46''W$.

DUNCAN W DURR

*Note: Found Nail @ Approx N $\frac{1}{4}$ Cor 16
Prodded but Did not find stone
Used NE cor to NW cor for N line of
my tract,*

