

N. 1/4 Cor., Sec. 1, T19S-R3W
Found: 1/2" rebar
Origin: unknown N^o

N.E. Cor., Sec 1, T19S-R3W
Found: 3/4" rebar
Origin: unknown

P.O. B

478.50'

$N90^{\circ}00'00''E$ (assumed)

Overland Road

2,643.57'

N 90° 00' 00" E 2,165.07'

N 40° 39' 19" W

149.84'

N 22° 50' 28" W

188.41'

$N 6^{\circ} 54' 31'' W$

119.02

N 89° 30' 36" W

257.40

$N 1^{\circ} 28' 26'' W$

741.72

32.1 Ac incl. R/W

Bertil H. and Patricia J. Ostlund
N.E 1/4, Sec 1, T19S-R3W

1802,04'

N 89° 14' 43" W

50°00'00"E

0-1

18th Avenue

2,639.44'

3.

Re

7

E. 1/4 Cor., Sec. 1, T19S R3W
Found: 1/2" rebar
Origin: unknown

Origin: unknown

Scale : $1'' = 220'$

Legend:

▲ = section corner found

- = 1/2" x 24" rebar with I.D. cap

P.O.B. = point of beginning

\$ = section line

$\mathcal{P}$ = property line

R/W = road right of way

For: Sandra S. Driggers

625 W. Garfield

Lindsborg, KS 67456

Date: December 3, 2007

Note: All bearings and distances are calculated/measured.

Heller Boundary Surveys, William B. Heller, L.S. 1202, 863 S. 9th, Salina, KS 67401, Ph: 1-620-245-8023 Pg. 2/2

Pg. 2/2