

Plat of Survey

Heller Boundary Surveys, W.B. Heller L.S., 863 S. 9th St., Salina, KS 67401
 Ph: 1-785-825-1898, Email: wheller@ks-usa.net

589°47'08"E 2626.91'

Chr. Cor. Sec 16,
 T17S-R3W

Found 1/2 rebar
 Origin: unknown

W. 1/4 Cor. Sec 16
 T17S-R3W
 Found 4" cut
 in concrete
 Origin: unknown

Found bolt

589°52'19"E

370.00(R) 370.58'(CM)

Found bent 5/8" rebar

Duane & Reba Becker
 Rev. Trust, Parcel in the
 S.W. 1/4 Sec 16, T17S-R3W
 BK 628, Pg 247
 BK 619, Pg 292
 BK 192, Pg 556

589°49'03"E

130.00'

0.27 AC
 excl. R/W

130.00'

90.00'

90.00'

90.00'

50°44'42"E

50°34'15"E

261.00'(R) 261.21'(CM)

Scale: 1" = 100'



Found bent 5/8" rebar & spike

589°47'08"E
 475.00(R) 472.43(CM)
 370.00'(R) 370.04(CM)

Found 1/2" rebar = P.O.B.

For: Duane & Reba Becker
 329 S. Jackson Street
 Lindsborg, KS 67456
 Date: 5-29-2007

S.W. Cor. Sec. 16, T17S-R3W
 Found 5/8" rebar w/I.D. cap
 Origin: KDOT

Legend:
 ▲ = section corner monument
 ● = Parcel monument
 ○ = 1/2" x 24" rebar & I.D. cap
 P.O.B. = point of beginning
 § = section line
 R = property line
 R/W = street right of way