

Heller Boundary Surveys, William B. Heller, P.L.S. 1202, Cell Ph: 620-245-8023, 863 S. 9th Street, Salina, KS 67401
Parcels in The S.E. 1/4 of Section 20, T17S-R4W
E 1/4 Cor, Sec. 20, T17S-R4W
Found: 5/8" rebar



- ▲ = Section Corner Found
- △ = Section Corner Set
- = Property Pin Found
- = 1/2" x 24" rebar & I.D. cap set
- ⊥ = Section Line
- ⌘ = Property Line
- (P.S.) = Previous Survey
- R/W = Public Road Right of Way

Date: February 4, 2020

Note: Field Work performed February 2020.

Note: All distances are calculated/measured distances.

