

I hereby certify this plat to be true, correct and complete representation of the property described as surveyed under my direct supervision on March 15, 2003.

Beginning 456.5' north of the Southeast corner of the Southeast Quarter Section 26, Township 19 South, Range 2 West of the 6th P.M. thence North $53\frac{1}{3}$ rods, West 160 rods, South $53\frac{1}{3}$ rods, and East to the point of beginning.



- Found $\frac{5}{8}$ " Rebar
- Set $\frac{1}{2}$ " Rebar

