


Survey for: John Jantz
 By: Garber Surveying Service, P.A.
 217 East First Ave., Suite #9
 Hutchinson, Kansas 67501
 316-665-7032

DESCRIPTION: Survey of parts of the NW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of Section 27,
 T.17 S., R.1W. of the 6th P.M. in McPherson County, Kansas,
 as described on the attached sheets



△ - Section subdivision corner found

▲ - Section subdivision corner set

● - Iron rebar set

S. 1/4 COR. SEC. 27.
T. 17 S., R. 1 W.

I hereby certify this plat to be a true, correct
 and complete representation of the property described
 above and on the attached sheets, as surveyed by me
 this 28th day of October, 1982.

Daniel E. Garber
 Daniel E. Garber, RLS

