Garber Surveying Service, P.A. 217 East First Ave., Suite #9 Hutchinson, Kansas 67501 DESCRIPTION: A tract in the S.E. 2 of Section 30, T.21 S., R.5 W. of the 6th P.M. as more particularly described on the attached sheet. N.4 COR SEC.30 T. 215. R.SW.  $\Delta$  - Section subdivision FOUND IRON PIN. corner found - 5/8"x24" capped rebar set 1"=100' SCALE: 5303. 510.00 90°04' 41' 6.00 ACRES 90 04 A1 510.00 2648.30 S.E. COR. SEC.30 5.4 COR. SEC. 30 T. 21 S. R.SW. FOUND IRON PIN. T. 218. R SW.; FOUND BROKEN L.S. ; SET 48 x24" IRON REBAR THROUGH CTR.

Survey for: David Willems

I hereby certify this plat to be a true, correct and complete representation of a survey made by me of the property described above and on the attached sheet this 14th day of September, 1981.

Daniel E. Garber, R.L.S.

LS-683

LS-683

LS-683