

Heller Boundary Surveys, W. B. Heller, L.S. 1202, 863 S. 9th, Salina, KS 67401 Ph: 1-620-245-8023

Date: March 9, 2010

N 89° 55' 00" W

2,640.44'

33' R/W

12th Avenue

N. 65, 40, 05

2,639.85

Vida J. Schrag, Trust

S.W. 1/4 and The W. 1/2, W. 1/2, S.E. 1/4
Section 31, T20S - R3W, less
Parcel # 2, 10.3 Acres.

See page 1/3 "Certificate of Survey" for
Legal Descriptions Parcel #1 & Parcel #2.

Found: 5/8" rebar & I.D. cap

Origin: Garber Surveying Service

$N90^{\circ}00'00''E$
(assumed basis of bearings)

Chisholm Road

S. 1/4 Cor., Sec 31, T20S-R3W, Found 5/8" rebar & I.D Cap, Origin: M. Thrower

Note: All distances are calculated/measured distances.

- N. 1/4 Cor., Sec 31, T20S-R3W
Found; 3/4" pipe
Origin: unknown

67401 Ph: 1-620-245-8023

N.E. Cor, sec. 31, T20S-R3W
Found: 3/4" pipe
Origin: unknown

E. 1/4 Cor., Sec. 31, T20S-R3W,
Set: 1/2 "x 24" rebar & I.D. cap
Origin: W.B. Heller

Scale: 1" = 440'

Legend

- ▲ = Section Corner Found
- Δ = Section Corner Set
- = 1/2" x 24" rebar in I.D. cap
- P.O.B. = Point of Beginning
- ⊥ = Section Line
- ⌘ = property Line
- R/W = Public Road Right of Way

S.E. Cor. Sec 31, T20S-R3W
Found: Stone Fragment 3.0' deep
Set: 1/2" x 42" rebar @ I.D. cap @ ctr stone

N.E. Cor., Sec. 6, T21S-R3W
Found: 5/8" rebar
Origin: unknown