

Note: All distances are calculated/measured distances.

Note: Field work performed July - August 2022.


Note: This survey is a retracement and client requests no pins be set on the abandoned Union Pacific Railroad right of way.

S.W. Cor., Sec. 5, T18S-R3W
(Found: 5/8" rebar
Origin: Forgy Surveying
P.O.B. Parcel #2

W. 1/4 Cor., Sec. 5, T18S-R3W
(Found: 5/8" rebar & I.D. cap
Origin: Garber Surveying Service
2,640.0' (G.L.O.)

William B. Heller, P.S. 1202, cell: 620-245-8023, email: willyboskilly@yahoo.com
863 S. 9th Street, Salina, KS 67401

Center Cor., Sec. 5, T18S-R3W
(Found: 5/8" rebar
Origin: Garber Surveying Service



Scale: 1" = 330'

Legend

- ▲ = Section Corner Found
- = 1/2" x 24" rebar & I.D. cap found
- = 1/2" x 24" rebar & I.D. cap set
- P.O.B. = Point of Beginning
- ⊥ = Section Line
- R = Property Line
- R/W = Public Road Right of Way
- G.L.O. = General Land Office

Date: August 1, 2022

For: Salvatore and Annamarie Brancaccio
4511 Rockland Drive
Arlington, TX 76016

S. 1/4 Cor., Sec. 5, T18S-R3W
(Found: 5/8" rebar
Origin: Garber Surveying Service