




Heller Boundary Surveys
William B. Heller, L.S. 1202
863 S. 9th St.
Salina, KS 67401
Ph: 1-620-245-8023

Survey for: Daniel G. Carlson
2951 13th Avenue
Lindsborg, KS
67401

Date: March 18, 2009

Legend:

- ▲ = Section Corner Monument
- = 1/2" x 24" rebar & I.D. cap set
- = 5/8" rebar found
- P.O.B. = Point of Beginning
- § = Section Line
- P = Property Line
- R/W = Public road Right of Way
- (R) = Record distance
- (m) = measured distance
- (cm) = calculated/measured distance