

SURVEYORS AFFIDAVIT

Survey of 7.02 acres more or less at 1120 26th Avenue, Canton, KS 67428 being a part of the SW1/4 of Section 4, T20S, R1W of the 6th P.M.

July 5, 2013

A correction to the November 13, 2009 survey at 1120 26th Avenue, Canton, KS 67428 filed at the Deeds Office in book 648 page 6040 due to the position of the Southwest Corner of Section 4, T20S, R1W being reset in error – another 5/8" bar was subsequently found which fits with past surveys to the south:

- 1. The SW Corner of Section 4, T20S, R1W is a 5/8" bar with references
 - 7.14' WNW to 1/2" Bar reset at incorrect reference distances
 - 49.25' NW to spike and tab in power pole
 - 43.20' SW to spike and tab in power pole
 - 53.10' SW to SE corner pipe fence
 - 8' West to center travel way N-S
 - 3' South to center travel way E-W
- 2. The surveyed line from the Southwest corner to the West Quarter Corner of Section 4, T20S, R1 W is 2628.08' with assumed bearing of N00°00'00"E instead of the distance of 2623.40'.
- 3. Per legal description of survey record, the tract is laid out from the Southwest corner, thence 975′, thence 670.00′, with a remainder to the West Quarter Corner of 983.08′ instead of 978.40′.

On July 8, 2013, the tract was resurveyed and pinned according to the legal description and survey of record, with the above corrections, for current owner David Skiba.

Melanie L. Thrower, PE LS CFM

DBA McPherson Engineering and Land Surveying Services

845 1800 Ave.

Abilene, KS 67410

(785) 479 2354