

Plat of Survey

Heller Boundary Surveys, W. B. Heller, L.S. 1202, 863 S. 9th, Salina, KS 67401 Ph: 1-620-245-8023


For: Robert W. Stambaugh
525 S. Main
Lindsborg, KS 67456

Parcels in the West 1/2 of Section 1, T17S-R4W

Date: April 30, 2010

N.W. Cor. Sec 1, T17S-R4W
Found: 5/8" rebar & I.D. cap
Origin: unknown

N. 1/4 Cor., Sec. 1, T17S-R4W
Found: 5/8" rebar; Origin: unknown



Scale: 1" = 330'

Legend

- ▲ = Section Corner Found
- = 1/2" x 24" rebar & I.D. cap set
- P.O.B. = Point of Beginning
- ⚡ = Section Line
- Ⓟ = Property Line
- R/W = Public Road Right of Way

