

Field Procedure: I searched for the following monuments: The North 1/4 Corner, the Northeast Corner, the East 1/4 Corner, the Southeast Corner, the South 1/4 Corner, the Southwest Corner, the West 1/4 Corner, the Northwest Corner and the Center Corner of section 14, T18S-R4W and only found the Northwest Corner, Northeast Corner and the East 1/4 Corner of said section in good condition. I sampled the physical evidence of said section and determined the positions of the North 1/4 Corner, Southwest Corner and West 1/4 Corner from physical evidence. I used a Nikon DTM-420 total station to read distances and turn angles. I set 5/8" x 24" rebars with plastic I.D. caps at the section corners I monumented. I set 1/2"x 24" rebars with I.D. caps at the property pins I monumented.