

Report of Survey

Research of the records of McPherson County Public Works revealed the following:

Surveys: G.L.O. notes and plats. Survey by County surveyor recorded Bk "A", pg. 306 thru 313, dated August 3rd 1903 where the exterior corners were recovered or re-set. Survey by Garber Surveying Service, P.A. dated, November 24th 1993, proj. # G93-1161. Survey by Guy Hall, County Engineer dated, December 29th, 1934. Witness ties to section 31-T20S-R4W and section 32-T20S-R4W, Section 6-T21S-R4W found at the McPherson County Public Works vault.

Field Procedure: I recovered the S.W. corner, the S. $\frac{1}{4}$ corner, the E. $\frac{1}{4}$ corner, and the N.E. corner of section 31-T20S-R4W. I also recovered the N.W. corner of section 6-T21S-R4W. I searched for the original monument at the S.E. corner of section 31-T20S-R4W and found nothing after digging a 15' x 10' hole 3' deep with a motor grader. I considered this corner lost and reset the corner using single proportion method. I also considered the N.E. corner and E. $\frac{1}{4}$ corner of section 31 for the N-S position of the S.E. corner of section 31. After sampling the