


222



- △ - Section subdivision corner
- - Iron pin found
- - Iron rebar set
- - Highway right-of-way marker

I hereby certify this plat to be a true, correct and complete representation of the property described above and on the attached sheet, as surveyed under my supervision, this 5th day of December, 1983.

Daniel E. Garber
Daniel E. Garber RLS #683



G83-231